



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/18018UE-1838/1

Work Order Type: Weatherization

Audit Name: 18018UE-1838

CLIENT INFORMATION

Client Name:

Address:

Client ID: 18018UE-1838

Alt. Client ID: Sullivan

AGENCY INFORMATION

Agency: Upper East Tennessee Human Development Agency **Agency Phone:** 246-6180

Address: 301 Louis Street

Fax:

Kingsport, TN 37662

Email Address: howardh@uethda.org

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Home built in 1997
home belly board in good condition.
Ceiling area need to be sealed (linear ft 500)
Wall plug pulled away from socket in wall (9)
Wall repair behind organ 3sq.ft.
Fix hole made by door handle (need stopper)
Seal tub with silicone caulk and around water fixture (client used 2 part foam still leaks).
replace none working exhaust fans bath (2)
Repair hole in bedroom (2 x 3)
repair bottom of wall as you enter the house (4' x 2").
50.8 pa @ 2910 target 2037
1200 sq.ft.
Has sign of leak in past living rm

Client Name:

Client ID: 18018UE-1838

Alt. Client ID: Sullivan

Work Order (Bid Form)

Work Order Name: WO/18018UE-1838/1

Report Run On: 3/30/2012

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 7

Measures

Measure 1 Fix wiring problem (walls)				Components			Inspected		
Comment							<input type="checkbox"/>		
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	fix receptical	Each	9	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
1	Health and Safety	Repair outlet recepticals	Each	9	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total: <input type="text"/>		
Field Notes:									

Measure 2 relief pipe				Components			Inspected		
Comment							<input type="checkbox"/>		
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	relief pipe	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
1	Health and Safety	install relief piping	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total: <input type="text"/>		
Field Notes:									

Client Name:

Client ID: 18018UE-1838

Alt. Client ID: Sullivan

Work Order (Bid Form)

Work Order Name: WO/18018UE-1838/1

Report Run On: 3/30/2012

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 7

Measure 3 Replace fan bathroom (Fan) #2				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	install fan	Each	1					
1	Health and Safety	Fix improper exhaust fan bath	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 4 smoke detector				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	install smoke detector	Each	1					
1	Labor	smoke dectector	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 5 General Air Sealing**Components****Inspected****Comment** Repai outlets in wall, outlet pulled☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	Seal 9 Ducts (mastic)	Each	9	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
1	Miscellaneous Su	General air sealing (setup cost)	Each	9	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Miscellaneous Su	seal ceiling crack along edge	Linear Foot	500	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Seal ceiling with silicone caulk	Linear Foot	500	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Construction Mate	Repair hole in living rm front wall (3 sq.ft.)	SqFt	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Labor	repair hole	SqFt	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
4	Miscellaneous Su	repair area around tub and faucet handle area about 3 ft.	Linear Foot	5	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
4	Labor	leaking area around faucet and around tub	Hour	2	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
5	Miscellaneous Su	repair hole in bedroom wall and were door knob hit	SqFt	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
5	Labor	repair hole in wall bedroom and door knob hole	SqFt	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
6	Labor	INSULATE AND CLOSE GAP AT BASE OF WALL	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
6	Miscellaneous Su	repair bottom seam of wall (3' X 2")	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Client Name:

Client ID: 18018UE-1838

Alt. Client ID: Sullivan

Work Order (Bid Form)

Work Order Name: WO/18018UE-1838/1

Report Run On: 3/30/2012

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 7

Other Detail

Measure Sub Total:**Sub Total:****Field Notes:****Measure 6 Lighting [Kitcher][3]****Components** LT1**Inspected****Comment**

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	Compact Fl. -13 Watt	Each	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
1	Lighting	Compact Fl. -13 Watt	Each	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 18018UE-1838

Alt. Client ID: Sullivan

Work Order (Bid Form)

Work Order Name: WO/18018UE-1838/1

Report Run On: 3/30/2012

DOE Weatherization Assistant

Version 8.6.0

Page 5 of 7

Measure 7 Lighting [Bedroo][2]**Components** LT2**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	Compact Fl. -13 Watt	Each	2	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
1	Lighting	Compact Fl. -13 Watt	Each	2	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 8 Lighting [Living rm][3]****Components** LT3**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact Fl. -13 Watt	Each	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
1	Labor	Compact Fl. -13 Watt	Each	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 18018UE-1838

Alt. Client ID: Sullivan

Work Order (Bid Form)

Work Order Name: WO/18018UE-1838/1

Report Run On: 3/30/2012

DOE Weatherization Assistant

Version 8.6.0

Page 6 of 7

Measure 9 Tune Cooling System**Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Cooling Equipmen	Cooling system tune up	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
1	Labor	Cooling system tune up	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 10 Vent fan (bath) #1****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Vent fan bathroom exhaust	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
1	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 18018UE-1838

Alt. Client ID: Sullivan

Work Order (Bid Form)

Work Order Name: WO/18018UE-1838/1

Report Run On: 3/30/2012

DOE Weatherization Assistant

Version 8.6.0

Page 7 of 7